

with Neutrik NC3MX 3pin XLR-connector (male) MK Battery - TPS-CH24-1,5 - ML24/1.5 (1.5 Ampere)





Green blinking: Green on (constantly): _ED-indication

Yellow on (constantly)

Battery charged completely AC on, no battery connected Charging

Inverse polarity

Red on (constantly):

Please only operate the device in dry and ventilated Please do not operate the device near heat sources. Caution

Please do not modify the output cable and connector. The device may only be maintained by trained personnel. cooms

pattery is connected and AC-power is connected. The charger starts charging automatically when the

- Charging stage: 28,8V
- Trickle charging, hysteresis curve

View: Connection side

(front), not solder side



Pin 2: - | (black) Pin 3: - | (black) Pin 1: + 24 < (70%)